

Name of Procuring Entity: EL SALVADOR CITY DIVISION Request for Quotation (P.R. No.): 2023-11-0342

REGION X - NORTHERN MINDANAO SCHOOLS DIVISION OF EL SALVADOR CITY

Revised	on:	Date:	Control	No. 202	3-11-104	
Standar	d Form/Title:	REQUEST FOR QUOTAT	ION End-User: El S	Salvador	City Division	
COMPA	ANY NAME:					
TEL NO	./FAX NO.:		TIN No.			
Conditio			ion duly signed by irn envelope attach	your rep	resentative n	
TERMS	and CONDIT	IONS:				
3. 4.	be attached uprocurement of manufacturer, supplier is a products/items. Bidders shall su the package, if Agency may proquotation.	ibmit original brochures showing o	ertificate shall the continuer is not the curer that the caler of the certifications of cipt of three (3)		EL C. NISTA Pairperson	L, PhD
Item No.		ITEMS & DESCRIPTION	DN	QTY	UNIT	PRICE
1	Repair of R	Ruby Building (2nd Floor- 1 2 Comfort Rooms)	Office Room and	1	320,000.00	
	*Repair of Roof and Ceiling					
	*Repaint 1 C	Office Room				
	*Replace Electrical System (if necessary)					
	*Repair of 2 comfort rooms					
	Note: P	lease refer to pre-repair in attached	spection report			
TOTAL ABC: Php 320,000.00				TOTAL QUOTATION:		
refer to	o Technical S	pecifications for details		4	110000	
	ving carefully at prices note	read and accepted your G above.	General Conditions,	I / We	quote you on	the
			-			



Address: Zone 3, Poblacion, El Salvador City J Tel No: (088) 882-6326 Website: <u>www.depedelsalvadorcity.net</u> Email: elsalvador.city@deped.gov.ph

Forging Partners





PRE-REPAIR INSPECTION REPORT

NAME OF THE PROJECT:	REPAIR OF RUBY BUILDING (2nd Floor- 1 Office Room and 2 Comfort Rooms)
BUDGET ALLOCATION:	Php 320,000.00
LOCATION OF THE PROJECT:	DIVISION OF EL SALVADOR CITY/RUBY BUILDING
FINDINGS:	1. THE ROOF AND CEILING NEEDS TO BE REPLACED DUE TO RECURRING
	ISSUE OF WATER INGRESS WHENEVER IT RAINS. 2. THE ROOM NEEDS TO BE REPAINTED SINCE WATER INFILTRATION HAS CAUSED UNSIGHTLY STAINS ON THE WALLS AND CEILING.
	3. THE ELECTRICAL SYSTEM NEEDS TO BE REPLACED (IF NECESSARY) BECAUSE IT MIGHT BE AFFECTED BY THE INGRESS OF RAIN INTO THE ROOM, WHICH CAN POSE SAFETY RISKS AND CAUSE DAMAGE TO THE ELECTRICAL COMPONENTS
	THE COMFORT ROOMS NEEDS TO BE REPAIRED BECAUSE OF THE FOLLOWING REASONS; A. DAMAGED DOORS WHICH COMPROMISE PRIVACY AND SECURITY.
	NON-FUNCTIONING SINK WHICH AFFECTS HANDWASHING AND HYGIENE. INOPERATIVE FLUSH THAT DISRUPTS PROPER TOILET FUNCTION. INON-WORKING FAUCETS HINDER ACCESS TO WATER WHICH HAMPER THE FUNCTIONALITY AND USABILITY OF THE COMFORT ROOMS.

Prepared and inspected by:

TONNIE JAE M. GONZALES

Ingineer iii

Recommending Approval:

ROULY B. LABIS

Funds Availability:

STEPHANIE P. SALIGUMBA OPA

Approved:

RANDOLPH B. TORTOLA Schools Division Superintendent